



Pre-amp measurement with no input (Using DAQ body to Pre-amp body connected grounding)

(Here for output pin 1 and 2)



Pre-amp measurement with no input (with DAQ body and pre-amp body connected ground)



Pre-amp measurement with no input (with DAQ body and pre-amp body connected to ground)

(Here for output pin 16 & 17)

