Mar. 19 Wednesday, March 19, 2014 Geoff, Libertock, Josh, Kabir, Mark Chris H., Uwab., Vince

- * Friday meeting: supports & integration 10:00 AM Friday.
- * PRAC Results all expected -internal review before remove CSI but not LHz target.
- * B-field will be done at her machine shop.
 - in press see pictures will start winding soon.

- I talked with Tim about running TOSCA.
- * RFSF Chris at UT yesterday. finishing up.

 will have in hand for mounting mtg.

 brass set screws, all there.

 I got a quote for a capacitor will order this wek.

 new Audio-Amp DC-75 not 75A

 Kabir to bring old audroump to UK for repair.

* Target - PCB's came in 2 days ago - all looks fine, low resistance traces.

- ready to start stringing need help. @ JINS lab. Kabir?
- Seppo debating caps 4 days memaster-carr.

* target pressure

- a) transverse: farther range b) longitudinal: use more of active volume.
- will fill first with the test breakdown sec cosmics w/ 4He?

saw " from air.

- Geoff: both committees recommend:

plan for working on 3H target don't want to deal with "crisis"

· can we use our gas handling system?

· Seppo? *

* preamps - pinout & cabling
- Kabir sent 32 & 24 ch pinout diagram to Mark
- Irakli measured pinouts: 44 pins for 18 ch.

· 2 ground pins from preamp #43,44 · test point (6 extra pins) #15,...

· cable did II chanels properly, 6 or 7 mixed.

- Vince - one person responsible for pins.

· lots of picces need to come together.

· Kabir & Irakli · both WC-preamp & preamp-cable

- pieces

: Irakli cheeked ADC - module.

· Mark: preamp wrong because of converter

· Cable: 90 degree plug.? · Vince — stay with D-sub connector — try and get twisted pairs same channels.

- schedule

Mar 24 - Diane gets back Apr 9 - APC arrives

- modifications

· chamber connection

· power converter module mounts - heat sink

· moved jumpers around · ability for resistor

- should resplice current cable.