




Noise measurement for shielded pre-amp with no input (Output pin 1 & 2)




Noise measurement for shielded pre-amp with no input (Output pin 1 & 2)




Noise measurement for shielded pre-amp with no input (Input pin 3 & 4 of J1)




Noise measurement for shielded pre-amp with no input (for pin 3 & 4 of J1)




Noise measurement for shielded pre-amp with no input (Output pin 16 & 17 of J1)



Noise measurement for shielded pre-amp with no input (Output pin 16 & 17 of J1)



Noise measurement for shielded pre-amp with no input (Output pin 1 & 2 of J3)



Noise measurement for shielded pre-amp with no input (for output pin 1 &2 of J3)

